


TO BE FILLED BY THE INSPECTING OFFICER
(ASSISTANT ENGINEER)

1. Name of the officer : ASSISTANT ENGINEER
LSGD SECTION, NENMANIKKARA G P
2. Name of School : JESUS ACADEMY SCHOOL THALORE
3. Period for which the certificate issued : 2023-2024
4. Nature of defect if any : NIL
- a. Foundation and Basement : 12Nos - 6.10 x 6.10 x 3.60 m
- b. Superstructure : 3Nos - 9.2 x 6.10 x 3.60 m
- c. Door and Window : 7Nos - 6.10 x 6.10 x 3.60 m
- d. Wood Work Wrought put up :
- e. Roof :
- f. Flooring :
- g. Miscellaneous cracks, etc. :
5. Any major defects noticed which will : NA
Render the building unsafe if any manner
6. Whether the maintenance works have been
Done Properly : YES
7. Whether the structure is sound or not f : Sound under normal weather
conducting classes and Climate condition


Notes:- 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood, etc.


2. Any additional observations are seemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school inspected by me on 25/05/2023 and found to be fit/unfit to conduct classes for the period 2023-2024 for the reason stated above.




Signature :
Designation :


ASSISTANT ENGINEER
Local Self Govt. Dept. Section
Nenmanikkara Grama Panchayat

Self attested


MANAGER
JESUS ACADEMY
THALORE, OLLUR-680 306
Ph: 0487-2351016


PRINCIPAL
JESUS ACADEMY
THALORE, OLLUR-680 306
Ph: 0487-2351016

